


## WorkMaster<sup>™</sup> & WorkMaster Jr.<sup>™</sup>

## Assembly Instructions

Tools required: Phillips screwdriver and drill with 1/8" drill bit (not included).





To Assemble: Unpack and inspect contents to confirm you have all parts listed above.

- Fasten floor glides (G) into bottom of leg frames (A) at each end as shown in *Figure 1*.
- 2

Place back panel (**C**) on a bench or table at least 20" high with ends hanging over the edge.

Hang left leg frame on top of back panel as shown in Figure 1. Make sure ends of back panel are snug against steel leg frames and holes are aligned in steel flange with pre-drilled holes in back panel. Attach using four 5/8" wood screws (J). Repeat step for right leg frame.






Carefully remove base assembly from table/bench and place upright on floor.

Place storage shelf (**D**) with predrilled holes facing up on the bench/table with ends hanging over edge. Lift base assembly carefully (may require two people) and set upside down on top of shelf. Balance with care. Align holes in steel flange with predrilled holes in shelf and insert 5/8" wood screws, making sure ends of shelf are snug against steel leg frames (see *Figure 2*). Tighten securely, but use care not to overtighten and strip.

Remove base assembly carefully from table/bench and place upright on floor.



©2012 ALVIN & COMPANY, INC. • P.O. Box 188, Windsor, CT 06095-0722 Phone: 860-243-8991 • Toll-Free: 800-444-2584 • Fax: 860-242-8037 • Toll-Free Fax: 800-777-2896