


95 Cantiague Rock Road, Westbury NY 11590 ph:516.931.9090 fax:516.931.1254 info@crystorama.com www. crystorama. com


MODEL#: 1543-CH ASSEMBLY AND DRESSING INSTRUCTIONS

IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEF ORE STARTING INSTALLATION







(GS10mmx4pcs+SS10mmx7pcs+14mmx4pcs+20mmx3pcs)X12pcs

(GS10mmx4pcs+SS10mmx5pcs+14mmx6pcs+20mmx2pcs)X12pcs

 $B = \overset{\bullet \bullet \bullet}{\bigcirc} & \overset{\bullet \bullet}{\bigcirc} & \overset{\bullet}{\bigcirc} & \overset{\bullet}{} & \overset{\bullet}{\bigcirc} & \overset$

(GS10mmx2pcs+SS10mmx4pcs+14mmx2pcs+20mmx2pcs)X12pcs

(GS10mmx1pc+SS10mmx2pcs+14mmx1pc+40mmx1pc)X1pc