1.0

7 Round Fusion Jack Canopy

CK007B-FJ_






GENERAL PRODUCT INFORMATION:




This product is suitable for indoor dry locations only.


This product can be dimmed with a standard incandescent dimmer.

Install the Canopy







Secure the mounting plate to the anchors with the provided #8 screws.



Insert one end of the safety cable into the mounting plate safety bracket and insert the other end into the housing safety bracket.



- Make sure the mounting plate is grounded in accordance with local electrical codes.
- Connect the housing white wire to the neutral power line wire with a wire nut.
- Connect the housing black wire to the hot power line wire with a wire nut.
- Place all wires and wire nut connections properly inside the housing.



- Slide the housing onto the mounting plate and line up the housing holes with the mounting plate holes.
- Replace and tighten the three #8-32 screws to secure the housing in place.

	F J	USION ACK POR	т	
•		۲		G
				FIXTURE —FUSION JACK

CAUTION: <u>RISK OF FIRE.</u> <u>Maximum</u> load per port is <u>75</u> watt. <u>Do Not Overload!</u>

Screw each fixture Fusion Jack completely into the Fusion Jack port.

Turn the power on.

SAVE THESE INSTRUCTIONS!



7400 Linder Ave, Skokie, IL 60077 800.323.3226 - 847.626.6300

www.lbllighting.com

© 2008 LBL Lighting. All rights reserved. The "LBL Lighting" graphic is a registered trademark of LBL Lighting. LBL Lighting reserves the right to change specifications for product improvements without notification. A Generation Brands Company