

PLUMBING REPAIR PARTS

SPEAKMAN®

Absolutely the best.

P.O. BOX 191 | WILMINGTON, DE 19899
www.speakmancompany.com

BALANCED PRESSURE VALVES - DIAPHRAGM TYPE

PART #	PRICE	PRODUCT DESCRIPTION
05-1634	\$ 2.20	Mark II temperature limit stop plate
10-0268	\$ 26.10	Wall plate for royal SR-1400 Series (stainless steel)
G05-0412-MO	\$ -	Please order RPG05-0843 unless OEM valve without Speakman trim & handle
G05-0413	\$ -	Please order RPG05-0843 unless OEM valve without Speakman trim & handle
G10-0063-PC	\$ 60.00	Mark II vc wall plate & vc handle (before 1/1/2007)
G10-0064-PC	\$ 65.00	Mark II diverter wall plate and handle (before 1/1/2007)
G48-0021-MO	\$ 4.50	Mark II screw & washer
RPG03-0259-RCP	\$ -	Please order RPG05-0843
RPG03-0362-MO	\$ 15.60	Diverter spindle (SM-1522)
RPG03-0371-RCP	\$ 17.40	Exposed shower spindle group (S-149X & S-159X)
RPG03-0372	\$ 2.20	Mark II vc spindle and o-ring (SM-1427)
RPG03-0373	\$ 16.80	Mark II spindle group (SR-16XX series)
RPG04-0296-PC	\$ 20.20	Regency/royal lever handle brass
RPG04-0367-PC	\$ 33.80	Handle for exposed showers
RPG04-0375-PC	\$ 21.50	Mark II volume control handle with lock nut
RPG04-0376-PC	\$ 26.60	Mark II diverter handle with lock nut
RPG04-0381-PC	\$ 28.10	Mark II brass lever handle (after 1/1/2007)
RPG05-0523	\$ 5.60	Bushing repair kit for G04-0244 handle
RPG05-0718	\$ 17.40	Mark II bonnet repair kit
RPG05-0719	\$ 14.50	Mark II bushing and o-ring kit
RPG05-0843	\$ 97.00	Mark II balanced/pressure cartridge (must have Speakman trim & handle)
RPG05-0846	\$ 97.00	Mark II balanced/regular cartridge 03-0500 spindle
RPG05-0847	\$ -	Mark II diverter cartridge
RPG05-1623	\$ 3.60	Spindle bushing repair kit
RPG10-0062-PC	\$ 41.00	Mark II Regency valve trim (before 1/1/2007)
RPG10-0079-PC	\$ 51.00	Regency Mark II vc/div wall plate assembly (after 1/1/2009)
RPG10-0080-PC	\$ 51.00	New Regency Mark II vc wall plate assembly (after 1/1/2007)
RPG10-0081-PC	\$ 71.30	New Regency Mark II div wall plate assembly (after 1/1/2007)
RPG10-0082-PC	\$ 37.80	New Regency Mark II wall plate assembly (after 1/1/2007)
RPG10-0083-PC	\$ 25.00	New plastic Mark II wall plate assembly (after 1/1/2007)
RPG20-1957	\$ 17.70	Spring check stop
RPG41-0088-MO	\$ 10.30	White index for volume control valve (before 1/1/2007)
RPG41-0089-MO	\$ 9.70	White index for standard valve (before 1/1/2007)
RPG41-0108	\$ 9.80	Mark II litho index repair group (after 1/1/2007)
RPG41-0109	\$ 8.90	Mark II litho VC index repair group (after 1/1/2007)
RPG41-0110	\$ 13.50	Mark II litho div index repair group (after 1/1/2007)
RPG41-0111	\$ 16.00	Mark II etch index repair group (after 1/1/2007)
RPG41-0112	\$ 13.50	Mark II etch vc index repair group (after 1/1/2007)
RPG41-0113	\$ 13.50	Mark II etch div index repair group (after 1/1/2007)
RPG41-0114	\$ 13.50	Mark II litho vc/div index repair group (after 1/1/2009)
RPG41-0115	\$ 13.50	Mark II etch vc/div index repair group (after 1/1/2009)
RPG49-0005	\$ -	Lower seals - new Mark II valve (after 1/1/2010)
RPG49-0076	\$ 2.20	Mark II spindle O-rings - 4 pack
RPG49-0126	\$ 4.10	Mark II bonnet O-ring
RPG49-0127	\$ 6.30	Quad ring repair group for Mark II - qty 2 (before 1/1/2010)

IMAGES

PLUMBING REPAIR PARTS

SPEAKMAN®

Absolutely the best.

P.O. BOX 191 | WILMINGTON, DE 19899
www.speakmancompany.com

BALANCED PRESSURE VALVES - DIAPHRAGM TYPE IMAGES



RPG49-0076



RPG49-0126



RPG49-0127



RPG41-0110



RPG41-0111



RPG41-0112



RPG41-0113



RPG41-0114



RPG41-0115



RPG49-0005



RPG10-0082-PC



RPG10-0083-PC



RPG20-1957



RPG41-0088-MO



RPG41-0089-MO



RPG41-0108




RPG41-0109



RPG05-0846



RPG05-0847



RPG05-1623



RPG10-0062-PC



RPG10-0079-PC



RPG10-0080-PC



RPG10-0081-PC



RPG04-0375-PC



RPG04-0376-PC



RPG04-0381-PC



RPG05-0523



RPG05-0718



RPG05-0719



RPG05-0843



RPG03-0259-RCP



RPG03-0362-MO



RPG03-0371-RCP



RPG03-0372



RPG03-0373



RPG04-0296-PC



RPG04-0367-PC



05-1634



I0-0268



G05-0412-MO



G05-0413



G10-0063-PC



G10-0064-PC



G48-0021-MO