

INSTRUCTIONS: Display Fixture
Model: DL-214

IMPORTANT SAFETY INSTRUCTIONS Lighted lamp is HOT:
WARNING – To reduce the risk of FIRE, ELECTRIC SHOCK, EXPOSURE TO EXCESSIVE UV RADIATION, and OR INJURY TO PERSONS:

1. Turn off/unplug and allow cooling before replacing bulb (lamp).
2. Bulb (lamp) gets HOT quickly! Only contact switch/plug when turning on.
3. Do not touch hot lens, or guard.
4. Do not remain in light if skin feels warm.
5. Do not look directly at lighted lamp.
6. Keep lamp away from materials that may burn.
7. Use only with a 50-watt or smaller bulb (lamp).
8. Do not touch the bulb (lamp) at any time. Use a soft cloth. Oil from skin may damage bulb (lamp).
9. Do not operate the luminaire with a missing guard.

SAVE THESE INSTRUCTIONS

Installing Lamp:

1. Use a 12V MR16-G or MR11-G (UV protected & glass covered lamp), 50watt maximum (purchase separately).
2. Align lamp pins with socket holes and gently press in.

Installing Clamp:

1. Installs on a firm flat surface, such as wood, particleboard, cubicle partition etc. Standard clamp accommodates surfaces ½” to 2 1/2” wide.
2. Use the angle adjustment knob on the side to change the angle.
3. Flexible arm allows multiple aiming angles

Accessories:

1. Supplied with standard clamp that opens to 2 ½’ wide.
2. An optional “DLC-4” clamp opens to 4”.
3. An optional DLC-P clamp works on 2 1/2” pipe
4. Various accessory lenses and lamp shields are available.