

# INSTRUCTIONS Quick Connect™ Track Transformer

Model: EN-HQ50AR / EN-LQ50AR / EN-JQ50AR

Read all instructions before installing.  
Switch off power before installing.

## Overview:


Transformers are designed for use on WAC 120V H, L or J series track. They accept WAC Quick Connect™ fixtures and pendants. They may also be used on other manufacturers' brand of track (consult factory for compatibility).

Transformers are electronic type, and may generally be dimmed with standard incandescent dimmers.

EN-HQ50AR (H Track): Rated 12 volt, 50-watt max.  
EN-LQ50AR (L Track) : Rated 12 volt, 50-watt max.  
EN-JQ50AR (J Track) : Rated 12 volt, 50-watt max.


## Installing the Quick Connect:

1. Place the metal decorative ring over the threads of the "QC" adapter.
2. Insert the male quick connect into the quick connect adapter.
3. Thread the top half of the conical section until it seats with the adapter.
4. Adjust fixture position; use caution not to loosen the conical section.



## Fixture Installation

1. Note the track head contacts, and the polarity groove running the length of the track.
2. The two contacts should be positioned so that when rotated, they will face the grooved side of the track (this is the side with two flat copper wires running its length).
3. Insert adapter into track slot. Rotate the adapter 90°.
4. Center the locking tab until it seats in the track slot.
5. Removal is the reverse procedure. Tracks may be positioned anywhere along the track length.



**WAC LIGHTING**  
Responsible Lighting®

Retain these instructions for future service and adjustments  
44 Harbor Park Drive  
Port Washington, NY 11050  
Tel: 800.526.2588  
www.waclighting.com